Oil Field Environmental Incident Summary

Responsible Party: Rud Transportation **Well Operator:** OXY USA INC.

Well Name: WILLIAM SADOWSKY 2-9-4H-142-96

Field Name: MANNING Well File #: 27957

Date Incident:9/25/2014Time Incident:05:00Facility ID Number:County:DUNNTwp:142Rng:96Sec:9Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

1141 Jery Ln

Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 9.5 Barrels 9.5 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/16/2014 Clean Up Concluded: 9/25/2014

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

Rud immediately recovered all standing liquids, any contaminated surface material will be removed at the completion of the frac.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 9/26/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.